

[Gå til hovedinnholdet.](#)

[Regulations](#)

[Notification and reporting](#)

[Published reports](#)

[Current investigations](#)

[Safety recommendations](#)



## Investigation of run-off-the-road accident with a bus on E10 at Åsvatnet in Hadsel

The Norwegian Safety Investigation Authority (NSIA) has initiated a safety investigation into the run-off-the-road accident with a bus on E10 on 26 December 2024. Three passengers died in the accident.

In the afternoon of 26 December 2024, a bus was traveling west on E10, from Narvik bound for Svolvær and Å in Lofoten. The bus belonged to Boreal Norge AS and it was full of passengers. The speed limit was 80 km/h at the site, and strong winds were reported.

Just before the bus was about to pass the intersection with county road 7644 Hanøyveien it went out of the roadway on the right side. The bus then drove through the road railings along Hanøyveien and down a steep slope to the lake Åsvatnet. The bus stopped at the bottom of the slope, leaning over to the right side, with the right front under water. Parts of the ice on Åsvatnet that were crushed in the collision came into the bus.

The investigation will clarify the sequence of events, identify safety issues and map the contributing factors to the accident and the extent of damage. Based on this, the NSIA will assess areas for improving safety.



*End position of the bus at the accident site on E10, with the right front in Åsvatnet. Photo: The*

*police*

## **Status of the investigation on 18 December 2025**

The investigation is still ongoing. Some work remains to be done with quality assurance of factual information, analysis and conclusions before the report can be finalized and published. The investigation is complex, with several involved parties and different investigation themes.

The NSIA has worked on clarifying the sequence of events on the day of the accident, from the start of the bus trip until after the rescue operation was completed. The NSIA has interviewed a number of people, including the bus driver, bus passengers, witnesses and emergency personnel. In addition, the NSIA has had meetings with the Norwegian Public Roads Administration (NPRA), the contractor, the bus company and the County Council. The NSIA has also sent questionnaires to other bus drivers and to passengers who have not been interviewed. The NSIA has scanned and visited the accident site on a number of occasions and carried out several simulations of the accident. The bus has also been investigated several times.

In addition, the NSIA has obtained a large amount of other factual information in the investigation, including:

- logs from emergency responders and the Traffic Control Centre
- management documents and procedures related to bus transport from Boreal Buss AS
- contract documents related to the bus transport from Nordland County Council
- medical data
- vehicle technical data and data from registration systems in the bus
- information regarding winter maintenance and contract documents from the NPRA
- data regarding road and traffic conditions
- data regarding weather, wind and driving conditions
- police documents

Based on the information gathered, the NSIA is working further on various investigation themes and the interaction between them. The themes being investigated include:

- road geometry and the road's side terrain
- weather and driving conditions, including assessment of wind and friction
- the road users' driving behaviour and experience
- bus safety, including damage of the bus construction, survival space and use of seatbelts
- organization, implementation and safety management of bus transport
- framework conditions for safety of bus transport

Even though the themes are being investigated, it is not given that the NSIA will find safety issues that end in safety recommendations within all the themes. It remains to be determined which focus areas the report will contain.

## Facts

Location	E10 Finnskarveien, Åsvatnet by Hanøyveien in Hadsel municipality
Occurrence date	26.12.2024
Accident type	Run-off-the-road accident
Road class	European road
County	Nordland
Vehicle type	Bus or coach
Type of Transportation	Passenger transport
Accident category	Accident with bus

*NSIA conducts its investigations for the sole purpose of improving transportation safety. The object of a safety investigation is to clarify the sequence of events and root cause factors, study matters of significance for the prevention of transportation accidents and improvement of transportation safety, and to publish a report with eventually safety recommendations. NSIA shall not apportion any blame or liability. Use of information from this investigation for any other purpose than for improvements of transportation safety shall be avoided.*